IDEA-0868 Copy 3 of 3

22 August 1962

	MEMORANDUM FOR: Execu	tive Officer, OSA-DD/R	
	SUBJECT : Monthly Commander's Report for July 62		
		raph No. 2, Commander's t of July 1962	25X1A
	Concerning engine	change required upon arrival of	
25X1A	article at The article concerned (342) was the		
	only aircraft available to ferry at the time due to the low		
	time remaining until inspection on the other stateside		
	assigned article. Article 342 had been throughly test		
	flown and checked out prior to ferry. The troublesome		
	engine removed from the aircraft is presently undergoing		
25X1A	test at to determine cause of malfunction.		
		- Cignera	25X1/
		Maintenance Officer Materiel Division OSA/DD/R	
25X1A	MD/OS A-DD/R:	rec	

2 - MD/08A 3 - RIB/08A